

# Final Reclamation and Stormwater Inspection

July 2, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 422524

Well Name: Miller #X31-04

Inspection Document #: 718600738

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Miller #X31-04  
Location ID: 422524



**Photo 1.** Looking north down the former access road. Desirable vegetation appears to have reached 80% coverage of the reference area.



**Photo 2.** Looking north from the access road across the well location. No oil and gas equipment remains on location.



Inspection Photos  
Location Name: Miller #X31-04  
Location ID: 422524



**Photo 3.** Looking north across the wellbore. Desirable perennial vegetation has established on location and appears to have reached 80% coverage of the surrounding reference area.



**Photo 4.** Looking west from wellbore. See photo 3 comments.



Inspection Photos  
Location Name: Miller #X31-04  
Location ID: 422524



**Photo 5.** Looking south from wellbore. See photo 3 comments.



**Photo 6.** Looking east from wellbore. See photo 3 comments.



Inspection Photos  
Location Name: Miller #X31-04  
Location ID: 422524



**Photo 7.** Looking south from the north edge across the location. The entire disturbance area including interim areas appears to have established desirable vegetation.



**Photo 8.** Reference vegetation to the east of well location. List C noxious weeds cheatgrass and mullein are present in the reference area, along with western wheatgrass and cereal rye.

