

Final Reclamation Inspection

June 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 418280

Inspection Document #: 718800495

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON H/35-11 TANK
Location ID: 418280



Photo 1. Photo taken of the tank battery location, facing east. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken of the tank battery location, facing south. See comments under Photo 1.



Inspection Photos
Location Name: CANNON H/35-11 TANK
Location ID: 418280



Photo 3. Photo taken of the tank battery location, facing southwest. See comments under Photo 1.



Photo 4. Photo taken of the tank battery location, facing north. See comments under Photo 1.

Inspection Photos
Location Name: CANNON H/35-11 TANK
Location ID: 418280



Photo 5. Photo taken of ground cover at the tank battery location. Photo illustrates bare ground and weedy annual vegetation, including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the reference area, located north of the tank battery location, facing east. Photo illustrates the location is dominated by sand sagebrush (*Artemisia filifolia*). .

