

# Final Reclamation Inspection

June 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 420047

Inspection Document #: 718800501

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: DECHANT STATE H/36-19 TANK

Location ID: 420047



**Photo 1.** Photo taken of the tank battery location, facing east. Photo illustrates that final reclamation activities have taken place, but gravel still remains on a portion of the site and vegetation has not established to Rule 1004 standards. Weedy annual vegetation is present across the location, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 2.** Photo taken from the tank battery location, facing southwest. See comments under Photo 1.



## Inspection Photos

Location Name: DECHANT STATE H/36-19 TANK

Location ID: 420047



**Photo 3.** Photo taken of the tank battery location, facing southeast. See comments under Photo 1.



**Photo 4.** Photo taken of the entrance to the tank battery location, facing east. Photo illustrates debris in the form of russian thistle (*Salsola tragus*).



## Inspection Photos

Location Name: DECHANT STATE H/36-19 TANK

Location ID: 420047



**Photo 5.** Photo taken of the tank battery location, facing Northwest. See comments under Photo 1.



**Photo 6.** Photo taken of ground cover at the tank battery location. Photo illustrates gravel remains on a portion of the site and cheatgrass (*Bromus tectorum*) was observed at the location.



Inspection Photos

Location Name: DECHANT STATE H/36-19 TANK

Location ID: 420047



**Photo 7.** Photo taken of the reference area to the tank battery location, located north of the location, facing north. Photo illustrates rye cropland.

