

Inspection Photos

July 10th, 2025

Operator: Catamount Energy Partners

Location ID: 438700

Inspection Document #: 714002295

La Plata County, CO

Township: NWSE 3 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Carpenter 32-6-3 2, 1S
Location ID: 438700

July 10, 2025
183° S



Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09914, 09918

Inspection Photos

Location Name: Carpenter 32-6-3 2, 1S

Location ID: 438700

July 10, 2025
212° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of western portion of the location which remains with bare, unvegetated soils. Large patch of field bindweed observed.

API #: 067-09914, 09918

Inspection Photos

Location Name: Carpenter 32-6-3 2, 1S

Location ID: 438700



Photo 3. Lube tank secondary containments at both pump jacks have no wildlife cover/protections.