

**Operator: CRESTONE PEAK RESOURCES OPERATING LLC**

**Location Name: OLIVE-62N66W 26SWSW**

**Loc ID: 318688**

**Inspection: 718600727**



**Exhibit A**



**Exhibit B**



**Exhibit C**

**CA:** The wellbore area does not meet final reclamation standards. The well appears to be located under an unused road. The road dead ends at a fence on the north side of the property. A small depression is present around the wellbore area. See attached pictures. Reclaim the road and wellbore area according to Rule 1004 standards. Remove gravel, decompact to a depth of 18 inches and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels.

**CA Resolution:** Operator has addressed the areas with rutting in the road in order to comply with Rule 1004.