

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7406 PAD

Location ID: 315085

Date: 07/11/2025



Photo # 9688 Entrance to location



Photo # 9712 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7406 PAD

Location ID: 315085

Date: 07/11/2025



Photo # 9690 Location



Photo # 9702 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7406 PAD

Location ID: 315085

Date: 07/11/2025



Photo # 9742 SE corner of location



Photo # 9743 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7406 PAD

Location ID: 315085

Date: 07/11/2025



Photo # 9745 NW corner of location



Photo # 9746 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7406 PAD

Location ID: 315085

Date: 07/11/2025



Photo # 9692 Wellhead sign lacks required information/not in compliance with CECMC rules



Photo # 9694 Equipment has been modified and is not being operated in a safe manner

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7406 PAD

Location ID: 315085

Date: 07/11/2025



Photo # 9697 Equipment has been modified and is not being operated in a safe manner



Photo # 9701 Fence is in disrepair

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK B 7406 PAD

Location ID: 315085

Date: 07/11/2025



Photo # 9724 Unused flowline does not comply with CECMC 600 & 1100 series rules



Photo # 9729 Hole in separator building/wildlife hazard/available for entry by wildlife