

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: CVR Production Pad 5-63-32

Loc ID: 332204

Inspection: 717900247



Exhibit A



Exhibit B



Exhibit C

CA: Tire rutting on site due to recent storm event. Operator to regrade site. Comply with Rule 1002.f.(2)

CA Resolution: Operator has addressed the areas with rutting in the road in order to comply with Rule 1004.