

Inspection Photos

06/02/2025

Operator: BONANZA CREEK ENERGY OPERATING
LLC- #8960

Location ID: 324584

Inspection Document #: 712300133

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: McCallum Unit # 24 Pad
Location ID: 324584



Photo 1. Photos 1-4 taken at the pad center, facing North, East, South and West illustrating the overview of the Location.



Photo 2. See comments under photo 1.



Inspection Photos
Location Name: McCallum Unit # 24 Pad
Location ID: 324584



Photo 3. See comments under photo 1.



Photo 4. See comments under photo 1.

Inspection Photos
Location Name: McCallum Unit # 24 Pad
Location ID: 324584



Photo 5. Photo illustrates utility pole on Location. Remove all utility equipment on, and leading up to the Location.



Photo 6. Debris remains on location.



Inspection Photos
Location Name: McCallum Unit # 24 Pad
Location ID: 324584



Photo 7. Photos 7-8 taken of the reference area vegetation southwest of the location, facing northwest and south. Vegetation is predominantly sagebrush and Indian Ricegrass.



Photo 8. See comments under Photo 7.

