

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 152-22 Pad

Location ID: 335193



Photo # 2479 From entrance to location



Photo # 2480 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 152-22 Pad

Location ID: 335193



Photo # 2481 Location



Photo # 2482 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 152-22 Pad

Location ID: 335193



Photo # 2483 Location



Photo # 2484 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 152-22 Pad

Location ID: 335193



Photo # 2485 Location



Photo # 2486 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 152-22 Pad

Location ID: 335193



Photo # 2487 Open hole with no BMP's/wildlife & personnel hazard



Photo # 2488 Open hole with no BMP's/wildlife & personnel hazard