

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Photo # 2834 From entrance to location



Photo # 2835 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Photo # 2836 Location



Photo # 2837 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Photo # 2838 Location



Photo # 2839 Staining near meter houses

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR-HEATH 130 Pad

Location ID: 322425



Photo # 2840 Cellar with cover on



Photo # 2841 Open hole with BMP's