

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 103 Pad

Location # 335633



Photo # 1958 From entrance to location



Photo # 1959 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 103 Pad

Location # 335633



Photo # 1960 Location



Photo # 1961 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 103 Pad

Location # 335633



Photo # 1962 Location



Photo # 1963 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 103 Pad

Location # 335633



Photo # 1964 Location



Photo # 1965 Debris