

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7423 PAD

Location ID: 316282

Date: 07/15/2025



Photo # 9880 Entrance to location



Photo # 9899 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7423 PAD

Location ID: 316282

Date: 07/15/2025



Photo # 9881 Location



Photo # 9889 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7423 PAD

Location ID: 316282

Date: 07/15/2025



Photo # 9906 NE corner of location



Photo # 9907 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7423 PAD

Location ID: 316282

Date: 07/15/2025



Photo # 9908 SW corner of location



Photo # 9909 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7423 PAD

Location ID: 316282

Date: 07/15/2025



Photo # 9883 Wellhead sign lacks required information/not in compliance with CECMC rules



Photo # 9896 Hole in meter house open to wildlife/available for entry by wildlife