

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7424 PAD

Location ID: 316285

Date: 07/15/2025



Photo # 9923 Entrance to location




Photo # 9934 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7424 PAD

Location ID: 316285

Date: 07/15/2025



Photo # 9924 Location



Photo # 9931 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7424 PAD

Location ID: 316285

Date: 07/15/2025



Photo # 9950 SW corner of location



Photo # 9951 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7424 PAD

Location ID: 316285

Date: 07/15/2025



Photo # 9952 NE corner of location



Photo # 9953 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7424 PAD

Location ID: 316285

Date: 07/15/2025



Photo # 9926 Wellhead sign lacks required information/not in compliance with CECMC rules



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources