



99999999

**OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- (001 - 09335)		LEASE NAME: Danford Champlin 23-8	
LOCATION: NESW 8-35-64W		OPERATOR: NARCO	
DATE: 8/21/96		INSPECTOR: LAR	
Insp. Type: SR	Insp. Status: DA	PA: (Y) N	Pass/Fail: (P) F Viol.: Y (N) NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	* Final DEA inspection * Well has been plugged and location restored	
Miscellaneous	No visible sign of wellsite in plowed field	

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00405507