

Final Reclamation Inspection

June 25, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 417842

Inspection Document #: 718800544

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON/X02-27 TANK
Location ID: 417842



Photo 1. Photo taken of the tank battery location, facing east. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the tank battery location, facing northwest. See comments under Photo 1.



Inspection Photos
Location Name: CANNON/X02-27 TANK
Location ID: 417842



Photo 3. Photo taken of the tank battery location, facing east. Photo illustrates that midstream equipment remains on location.



Photo 4. Photo taken from the tank battery location, facing north. See comments under Photo 1.

Inspection Photos
Location Name: CANNON/X02-27 TANK
Location ID: 417842



Photo 5. Photo taken of midstream equipment that remains on location and is in disrepair.



Photo 6. Photo taken of ground cover at the location. Photo illustrates bare ground and weedy annual vegetation including russian thistle (*Salsola tragus*).



Inspection Photos
Location Name: CANNON/X02-27 TANK
Location ID: 417842



Photo 7. Photo taken of the access road to the tank battery location, facing west. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 8. Photo taken of the reference area to the well location, northwest of the location, facing northeast. Photo illustrates the site is dominated by sand sagebrush (*Artemisia filifolia*).

